

IMPORTANT PRODUCT RECALL NOTICE

Feb 6th, 2018

Milton Industries is contacting you because our records reflect that you recently purchased the ColorFit V Style couplers, Models Nos. s-303VKIT, s-305VKIT, s-307VKIT, s-314VKIT ("the Product"). The Product in question is purple and steel in color and design.

I M P O R T A N T

Your V Style ColorFit coupler is being recalled.

You should discontinue using and/or reselling the Product immediately and return all units to Milton Industries (see "What should you do?" below) [If you have already resold some or all of the Products you purchased from Milton Industries, please see "How to Handle End User Units" below.]

Why is a recall being conducted?

Milton Industries recently learned that one user of the Product experienced a loosening of the torque threaded base portion of the coupler. If the base were to separate completely from the coupler, the plug could separate and the attached hose could make a whipping motion, depending on the level of PSI flowing from the compressor, which could present a safety issue. In an abundance of caution, Milton Industries is recalling this Product to ensure that no similar loosening incidents occur.

Will I receive replacement couplers?

Yes. Upon receipt of the return of your ColorFit V Style coupler, Milton Industries will ship to you within four weeks, free of charge, new Product that has been tested to ensure that there is no loosening issue. *New ColorFit V Style couplers and kits are available for order effective immediately.*

What should end users do?

Visit <http://miltoninfo.com/return> to initiate the recall process. If you do not have access to the internet, contact Milton Industries customer service dedicated recall number at 866-408-4951 to request a prepaid UPS shipping label to return your Product.